



AP-IP150™ BcN IP Phone

High Performance Broadband Convergence Network
IP Phone Solution

Smart Web based Easy Setup



AddPac

AddPac Technology

2007, Sales and Marketing

Content

- Web Interface Features
- Web Interface Tree Structure
- Web based Management
 - Welcome Page
 - System Information
 - Network Setup (WAN Setup)
 - Speed-Dial information
 - VoIP Common Configuration
 - SIP (Session Initiation Protocol)
 - MGCP (Media Gateway Control Protocol)
 - H.323 (ITU-T H.323 Protocol)
 - Auto Upgrade
 - APOS™ Upgrade via HTTP


Web Interface Features

AP-IP150 IP Phone

- User-friendly interface
- Support Easy Setup for Basic Configuration
 - System (System Information, Time Zone, System Users)
 - Network (WAN, LAN, Tunneling, Static NAT)
 - SpeedDial
 - VoIP Setup (Common, H.323, SIP, MGCP)
 - Application (Telnet, HTTP, SNMP, Syslog, NTP, STUN)
- Support User Authentication & Service
 - Configuration Save and System reboot
 - Open Virtual Terminal via Telnet
 - Access Control according to user access level
 - Auto-Upgrade (APOS™ Upgrade via HTTP)
 - E-mail


Web Interface Structure 1/3

AP-IP150 IP Phone




Web Interface Structure 2/3

AP-IP150 IP Phone



Web Interface Structure 3/3

AP-IP150 IP Phone



Web based Management

AP-IP150 IP Phone

- Welcome Page
- System Information
- Network Setup (WAN Setup)
- Speed-Dial information
- VoIP Common Configuration
- SIP (Session Initiation Protocol)
- MGCP (Media Gateway Control Protocol)
- H.323 (ITU-T H.323 Protocol)
- Auto Upgrade
- APOS™ Upgrade via HTTP

AddPac



VoiceFinder IP150

System

Network

Speed Dial

VoIP

SIP

MGCP

H.323

Service

Auto Upgrade

Status




AP-IP150 IP Phone



파일(F) 편집(E) 보기(V) 즐겨찾기(A) 도구(I) 도움말(H)

주소(D) <http://172.16.8.114/>

미동 연결 >

AddPac**VoiceFinder IP150****System**

Network



Speed Dial




VoIP



SIP



MGCP



H.323



Service



Auto Upgrade



Status

System Information

APOS(tm) Kernel version 8.41.001

Copyright (c) 1999-2006 AddPac Technology Co., Ltd.

IP150 uptime is 0 days 00:20:42

IP150 current time is Thu Jan 1 00:20:42 1970

System image file is "flash:/ip150_g2_v8_41_001.bin"

IP150_G2 System software Revision 8.41.001

Released at Wed Nov 15 13:20:20 2006

Program is 2630208 bytes, checksum is 0x1484f7df

32BIT RISC Processor With 112MHz Clock

16 Mbytes System Memory.

512 Kbytes System Boot Flash Memory

4 Mbytes System Flash Memory

1 RS232 Serial Console Interface

2 Ethernet/IEEE 802.3 Interface (100BaseTX)

Board Rev 0

Maximum number of mbufs is 512, 255 mbuf is free.

System CPU utilize is 11 percent.

Heap Memory is 16384 kbytes, 16121 kbytes is used, free is 263 kbytes.



System

Network

Speed Dial

VoIP

SIP

MGCP

H.323

Service

Auto Upgrade

Status

WAN Setup

		IP Address <input type="text" value="172.16.8.114"/> A.B.C.D
		Network Mask <input type="text" value="255.255.0.0"/> A.B.C.D
	<input checked="" type="radio"/> Static IP	Default Router <input type="text" value="172.16.1.1"/> A.B.C.D
		DNS Server <input type="text" value="61.33.161.2"/> Primary DNS Server
		<input type="text" value="168.126.63.1"/> Secondary DNS Server
	<input type="radio"/> PPPoE(ADSL)	Username <input type="text"/>
		Password <input type="text"/>
		Authentication <input type="radio"/> None (No Authentication)
		<input type="radio"/> PAP (PPP Authentication Protocol)
		<input type="radio"/> CHAP(Challenge Handshake Authentication Protocol)
		Service Name <input type="text"/> (optional)
	<input type="radio"/> DHCP	<input type="checkbox"/> Enable Auto Renew
		Maximum renew time <input type="text"/> (in seconds)

MAC(Hardware) Address MAC address clone, (optional) Enable QoS (optional)Qos bandwidth kbps (default auto, 48-4096)QoS PPS pps (default auto, 20-2000)

AddPac**VoiceFinder IP150**

System

Network

Speed Dial

VoIP

SIP

MGCP

H.323

Service

Auto Upgrade

Status

Speed Dial Information

Number	Phone Number	Name	Control
1	8225683848	AddPac&Technology&Co.,&Ltd.	<input type="button" value="delete"/>
			<input type="button" value="add"/>

- System
- Network
- Speed Dial
- VoIP
- SIP
- MGCP
- H.323
- Service
- Auto Upgrade
- Status

VoIP

- [SIP\(Session Initiation Protocol\)](#)
- [MGCP\(Media Gateway Control Protocol\)](#)
- [H.323\(ITU H.323 Protocol\)](#)

Phone number

 (E.164 number)

g711ulaw : G711 u-law Codec Type(64 kbps) ▾

g711alaw : G711 a-law Codec Type(64 kbps) ▾

g729 : G729 Codec Type(8 kbps) ▾

g7231r63 : G723.1 Codec Type(6.3 kbps) ▾

Preferred voice codec

Enable Call waiting

No Yes

Fax Mode

T.38 inband T.38 bypass

Fax Rate(bps)

9600 2400 4800 7200

12000 14400 disable

Enable Caller ID

No Yes

Enable Vad

Yes No

Enable Sid

Yes No

Input Gain


0 (default 0, between -18 to 9)

Output Gain

0 (default 0, between -18 to 9)

Default(Inband)

via RTP(RFC2833)



AddPac | 🏠 | 🌐 | 📈 | 📊 | 🌐 | 📱 | **VoiceFinder IP150**

System **Network** **Speed Dial** **VoIP** **SIP** **MGCP** **H.323** **Service** **Auto Upgrade** **Status**

MGCP (Media Gateway Control Protocol)

Endpoint Local name / /
(default 0/0, set local name of endpoint)

Endpoint Domain name (IP address or domain name)

Primary Call agent Server address and Port (default 2427)

Secondary Call agent Server address and Port (default 2427)

MGCP Enable Yes No

Restart Delay (default 0, between 0 to 20)

Local Lingback tone play No Yes (if "Yes", it forced to play local ringback tone toner)
 Default(Inband)
 via RTP(RFC2833)
 via Signal(out-of-band)
 Dual(both RTP & Signal)

© ADDPAC TECHNOLOGY 2007. ALL RIGHT IS RESERVED.

- System
- Network
- Speed Dial
- VoIP
- SIP
- MGCP
- H.323
- Service
- Auto Upgrade
- Status

H.323 (ITU H.323 Protocol)

Primary Gatekeeper	<input type="text" value="gk1.addpac.com"/>	<input type="text" value="1719"/>	Server address and Port (default 1719)
Secondary Gatekeeper	<input type="text" value="gk2.addpac.com"/>	<input type="text" value="1719"/>	Server address and Port (default 1719)
H.323 ID	<input type="text" value="voip.172.16.8.114"/> (H.323 Identifier string)		
H.323 Password	<input type="text" value="*****"/> (H.323 password string)		
Security Option	<input checked="" type="radio"/> Enable with MD5 <input type="radio"/> Enable with MAC <input type="radio"/> Disable		
H.323 Technical Prefix	<input type="text"/> ([0-9#*] gatekeeper registered prefix)		
Registration	<input type="radio"/> Yes <input checked="" type="radio"/> No		
Local H.323 port	<input type="text" value="1720"/>	(default 1720, between 1 to 65535)	
H.323 RAS port	<input type="text" value="22000"/>	(fixed the RAS source port, between 1 to 65535)	
Register Expiration	<input type="text" value="60"/>	(in seconds, default 60, between 10 to 86400)	
H.323 Call start mode	<input checked="" type="radio"/> Fast <input type="radio"/> Slow <input type="radio"/> Preferred slow		
H.323 Tunnel mode	<input checked="" type="radio"/> Enable <input type="radio"/> Disable		
Keep Registration	<input checked="" type="radio"/> No <input type="radio"/> Yes (Keep Registration on rejected gatekeeper)		
NAT Support Method	<input checked="" type="radio"/> No <input type="radio"/> With LCF		

Update



System

Network

Speed Dial

VoIP

SIP

MGCP

H.323

Service

Auto Upgrade

Status

Application Service

Enable Telnet Server Port (default 23, 1-65535)

Enable HTTP Server Port (default 80, 1-65535)

Enable FTP

Control Port (default 21, 1-65535)

Data Port (default 20, 1-65535)

Enable Syslog

Log Server Primary Log Server address and Port (default 514)

Log Server Secondary Log Server address and Port (default 514)

Log Level ▾

Enable NTP

NTP Server Primary NTP Server (Hostname or A.B.C.D)

NTP Server Secondary NTP Server (Hostname or A.B.C.D)

Interval NTP time resynchronize interval, in hour (default 24 hours)


Enable STUN

STUN Server 3478 STUN Server address and Port (default 3478)

AddPac



VoiceFinder IP150




Network



VoIP



MGCP



Service



Status

Auto Upgrade

URL <http://download.addpac.com/AP150/packing.lst> (auto upgrade server URL)

Login addpac (optional)

Password (optional)

Authentication Basic Digest (MD5)

Success 1 Days 0 Minutes

Interval Minutes

Auto Reboot (reboot system when upgrade is finished)

Plant Websoft Websoft system - version 3

Update

http://172.16.8.114 Smart Management System - Microsoft Internet Explorer

파일(F) 편집(E) 보기(V) 즐겨찾기(A) 도구(I) 도움말(H)

뒤로(←) 뒤로(→) 검색(🔍) 즐겨찾기(⭐) 주소(D) http://172.16.8.114/ 이동(↗) 연결(🔗)

AddPac | VoiceFinder IP150

System Network Speed Dial VoIP SIP MGCP H.323 Service Auto Upgrade Status

Upload IP150 S/W

Filename (*.bin): 찾아보기... upload

© ADDPAC TECHNOLOGY 2007, ALL RIGHT IS RESERVED.

AP-IP150 IP Phone

Thank you!

AddPac Technology Co., Ltd.
Sales and Marketing

Phone +82.2.568.3848 (KOREA)
FAX +82.2.568.3847 (KOREA)
E-mail sales@addpac.com